











ASSEMBLY INSTRUCTION


MODEL : HT TRUNDLE

NO.	PART LIST	QTY
A		2 PC
B		2 PC
C		10 PC


NO.	HARDWARE LIST	QTY	NO.	HARDWARE LIST	QTY
1	JCBC M6 x 50mm 	4PC	5	WOOD DOWEL 	8PC
2	BARREL NUT 	4PC	6	CASTER 	4PC
3	CSK M4 x 25mm 	24PC	7	ALLEN KEY 	1PC
4	CSK M3.5 x 12mm 	8PC			

STEP 1


(i)




STEP 2



STEP 3



STEP 4



ASSEMBLY COMPLETED

