

Assembly Manual




STEP 1:




Lay Part A with holes facing up on flat surface. Parts D screw to Part A using Part F,Part H and Part J

STEP 2




Lay Part B with holes facing up on flat surface. Parts E screw to Part B using Part G,Part H and Part J

STEP 3



Put Part C on the top of Part A

STEP 4



Completed.