

Assembly Manual

A



1 PC

B




1 PC

C




4 PCS


D



4 PCS



Step 1:Lay Part A with holes facing up on flat surface



Step 2:Parts C screw to Part A



Step 3:Put Part B onto Parts C



Step 4:Parts D screw to Part B