


A
X52




B
X20




C
X6




D
X32




E
X4




F
X4



G
X4




H
X4




I
X4




J
X1




K
X1




L
X1




M
X1



N
X1




O
X1






P
X1

1




2







5



6



7



8

