













## COMPONENT PARTS

## FITTINGS



- Ⓐ  Bolt x 4
- Ⓑ  Bolt x 2
- Ⓒ  Plate x 1
- Ⓓ  O-ring x 1
- Ⓔ  Roll x 1
- Ⓕ  O-ring x 1
- Ⓖ  Roll x 1
- Ⓗ  O-ring x 2
- Ⓘ  Space part x1
- ⓵  \*1
- Ⓚ  Screw cap x 1

## COMPONENT CHECKLIST

PART	No.	Qty.	
Cushion	01	1	<input type="checkbox"/>
Seat	02	1	<input type="checkbox"/>
Base	03	1	<input type="checkbox"/>

## TOOLS REQUIRED



Allen key (supplied)



Spanner (supplied)