

















Assembly instruction sheet

HT-5019



	1		2		1		E		A
							F		B
					1		1		C
	1		1		5		1		D
								M6*40 X 6	
								M6*25 X 2	
								M6*20 X 4	
								M8*20 X 4	