




# LEGS INSTALLATION INSTRUCTION



Leg position of the chair



legs\*2PCS




Metal Gasket 16pcs



Screw 8pcs



Wrench 1pcs



Insert the hex socket cap screws into the threaded hole