















WI10304



Parts List


①= 1PC	②= 1PC	③= 2PC	④= 1PC	⑤= 2PCS
				
⑥= 1PC	⑦= 1PC	⑧= 1PC		
				

Hardware Included

A= 17PCS	B= 20PCS	C= 2PCS	D= 2PCS
			
E= 1PC			
			


- Fix Part 3,4,and 5 to Part 1 with screw B.

1




- Fix Part 2 to Part 3,4 and 5 with screw B.


2



3 • Fix Part 6 to the frame with screw A.




4 • Fix Part 7 to the frame with screw A.



- Fix Part 8 to the frame with screw A.

5



- 6** •Screw hardware C and D to the frame, then use hardware E to fix them.

