

A



1PC

B



2PCS

C



4PCS

D




4PCS

E



1PC

### Assembly Manual



Step 1: Lay Part A with holes facing up on flat surface



Step 2: Parts B screw to Part A using Parts C , Parts D and Part E