



A



1PC

B



2PCS

C



1PC

D



10 PCS

E



10 PCS


F




1PC

Assembly Manual

Step 1: Lay Part A with holes facing up on flat surface



Step 2: Parts B screw to Part A using Parts D, Parts E and Part F



Step 3: Part C screws to Parts B using Parts D, Parts E and Part F