
Α		4PCS		ூற்றிற்றி M6×45mm	16PCS	
В		4PCS	J	M6×40mm	8PCS	
С		4PCS	K	4mm	1PC	
D		4PCS				S
E		4PCS				(l a L
F		4PCS				
G		4PCS				
Н	⊚∭ M6×12mm	24PCS				


## **ASSEMBLY INSTRUCTION**

\*\*\*DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED\*\*\*




Step 1-Use screws(Part H/J)to connect chair feet(Part C/D) with cross-bars (Part F) Insert G into the holes of Part F and Part E,

Use screws(Part J)to connect chair feet(Part C/D) with cross-bars(Part E) as a metal chair frame




Step 2-Use screws(Part H) to connect the chair metal frame with the backrest(Part A)
Use screws(Part I)to connect seat(Part B) with the chair metal frame

**X**4



## **ASSEMBLY INSTRUCTION**

\*\*\*DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED\*\*\*



Step 1-Use screws(Part D)to connect cross-bars (Part C) with table feet(Part B) as table metal frame

Step 2-Use screws(Part D)to connect table metal frame with the table top(Part A)

