

# Assembly Manual



1PC




4PCS


E



8PCS



Step 1: Lay Part A with holes facing up on flat surface



Step 2: Parts B screw to Part A using Parts E, Parts F and Part


F



1PC



8PCS



Step 3: Put Part C onto Parts B

G



4PCS



1PC



Step 4: Parts D screw to Part C