

Assembly Manual




1PC

E



4PCS



3PCS

F



7PCS

G



1PC


H




1PC




1PC




Step 1: Lay Part A with holes facing up on flat surface



Step 2: Parts B and Part C screw to Part A using Parts F , Parts G and Part H



Step 3: Put Part D onto Parts B and Part C



Step 4: Parts E screw to Part D