Read this instruction carefully. See hardware and furniture part list for guidance. Be sure all parts are complete, before you assemble. Place all wooden furniture parts on a clean and flat soft surface to prevent from being scratched. Follow the figure to start assembling.


PART LIST				
ITEM	DESCRIPTION	BOX	QTY	
Α	CHAIR	1	1 PC	
В	LEG	1	4 PCS	

HARDWARE LIST (BOX :1)			
ITEM	TEM DESCRIPTION		QTY
1	JCBB BOLT M8 x 50mm	@	8 PCS
2	M8 FLAT WASHER	0	8 PCS
3	M8 SPRING WASHER	0	8 PCS
4	M5 ALLEN KEY (BALL SHAPE)	ſ	1 PC

- CAUTION: 1. Do not FULLY TIGHTEN the nuts or nuts bolts until they are ready for assembly.
 - 2. Do not OVER TIGHTEN the nuts or bolts to avoid causing damages to the thread.
 - 3. Keep all hardware parts out of reach of children.


NOTE: THE LIST AND QUANTITY SHOWN ARE FOR 1 UNIT ASSEMBLY.


Tools needed: Screwdriver (not provided).



STEP 3

Place the chair on the flat surface and adjust the alignment and balance of the legs then, Please screw tight the steps 1 bolts.





Read this instruction carefully. See hardware and furniture part list for guidance. Be sure all parts are complete, before you assemble. Place all wooden furniture parts on a clean and flat soft surface to prevent from being scratched. Follow the figure to start assembling.


PART LIST			ı	
ITEM	DESCRIPTION	BOX	QTY	
Α	CHAIR	1	1 PC	ŀ
В	LEG	1	4 PCS	

HARDWARE LIST (BOX :1)			
ITEM	DESCRIPTION		QTY
1	JCBB BOLT M8 x 50mm	aaaaa⊏()	8 PCS
2	M8 FLAT WASHER	0	8 PCS
3	M8 SPRING WASHER	0	8 PCS
4	M5 ALLEN KEY (BALL SHAPE)	ſ	1 PC

- CAUTION: 1. Do not FULLY TIGHTEN the nuts or nuts bolts until they are ready for assembly.
 - 2. Do not OVER TIGHTEN the nuts or bolts to avoid causing damages to the thread.
 - 3. Keep all hardware parts out of reach of children.

NOTE: THE LIST AND QUANTITY SHOWN ARE FOR 1 UNIT ASSEMBLY.

Tools needed: Screwdriver (not provided).



STEP 3

Place the chair on the flat surface and adjust the alignment and balance of the legs then, Please screw tight the steps 1 bolts.

